

SOB Keyboard Shortcuts

- [R] enter Manual Target position Report
- [S] **Race Start** form
- [Shift-T] **Tidal Stream** predictions tool
- [Ctrl-T] Toggle **Tides and Tidal Streams** display On/Off

- [Space] Refresh chart display and tool drawings, centre ship.
- End auto-centre mode (if enabled)
- [Space+Space] place Wpt at ship's position
- [Arrow keys] pan the chart
- [Enter] Quick Object Info mode
- [I] and [O] zoom in and out
- [Enter] , [Space] enable Auto Centre mode
- [Backspace] PastTrack form
- [Tab] Dampen & Calibrate form
- [Alt+Space] Go to exact position
- [Ctrl+Space] Show Talking Pilot form
- [Ctrl-A] toggle Animated Lights
- [Ctrl-G] toggle Graticule
- [Ctrl-M] start Man Overboard mode
- [Ctrl-R] Reset the chart display

- [Ctrl-Shft-Y] Show isomagnetic graph (Mag Var)
- [J] & [K] change Year used for MagVar graph

- [F1] **Help Screen** list of keyboard shortcuts
- [F2] Toggle **Chart Levels** Toolbar
- [F3] Toggle **Chart Toggles** Toolbar
- [F4] Toggle Depth Shading
- [F5] Display Depth Spot Soundings
- [F6] Toggle Chart **MixLevel** Mode
- [F7] **Night-Mode** Settings
- [F8] Toggle **Declutter** Mode
- [F9] Display **Ship's Settings** Form
- [F10] **AllWaypoints** Form
- [F11] **AllRoutes** Form
- [F12] Toggle Perspective View

- [A] start/stop Anti-Grounding
- [B] show Chart Borders form
- [C] hide/show Cursor Box
- [D] start/stop Dead Reckoning
- [L] [R] steer the ship Left or Right
- Press [Shift] to toggle 1° or 10° steps
- [+] [-] add or subtract 2.5kn to speed
- [F] toggle Fastdraw mode (rarely used)
- [G] toggle **GRIB Viewer**

- [+] [-] cycle loaded F'cast periods
- [B] toggle Wind arrows big/small
- [N] display the **Raw NMEA Data** form
- [P] hide/show Printing tools
- [T] display the **Targets** form
- [V] hide/show View Panel menu
- [W] toggle Wind Tools

- [1] Hide/Show Main toolbar
- [2] Hide/Show Status Bar
- [3] Perspective View (3D View)
- [4] Depth Shading form (use with [F4])
- [PgUp,PgDn, Home, End]
- Set depth area colouring
- [Ctrl+F4] cycle alternative chart palettes
- [Shift+F4] show highlighted depth range
- [5] Toggle Pointer colour (Blue/Yellow)
- [6] Toggle Datum Shift
- [7] Toggle Ship's Bells
- [8] virtual-zoom mode (rarely used)
- [9] Fixed-Scale/Level-Changing zooming
(rarely used)
- [0] (zero) Reset chart scale